

ABSTRACT

Description Of Flood Location In Central Tanjung Karang District Bandar Lampung 2011-2013

By:

Iis Kurniati

This research aims at (1) finding out where the location of flood in Central Tanjung Karang Bandar Lampung in 2011-2013, (2) describing the condition of declivity at the location, (3) describing the land usage at the location, (4) describing the type of soil at the location, (5) describing the cause of flood.

The research used descriptive method, with documentation and observation as the data collecting technique. In term of data analyzing technique, the writer used analistic descriptive technique.

The conclusions drawn in the research are (1) the locations of flood in Central Tanjung Karang district in 2011-2013 were Durian Payung, Pasir Gintung, Kaliawi, Kelapa Tiga and Gotong Royong subdistrict, (2) the declivity at the flood locations was the area located in category 0-8% (flat area), (3) the land usage at those locations were dominated by residence, trade, and service, (4) the type of soil at the locations was latosol, (5) the main cause of flood was the change of land usage system.

Keywords: flood, central tanjung karang district, location